

Date	LAKE	Site	pH	Temp	Dissolved Oxygen	T Dissolv'd Solids	Turbidity	E.Coli	Nitrate	Total Phosphorus	T Suspend Solids
9/7/2011	Adams	11	9.04	20.2	8.22	205	1	50	0.2	0.05	4
9/7/2011	Atwood	18	8.89	20.6	8.37	244	2	0	0.4	0.1	9
9/7/2011	Big Long	8	8.40	17.8	5.45	222	5	0	0.2	0.18	16
9/7/2011	Big Turkey	6	8.57	19.4	7.32	267	2	50	0.3	0.11	5
9/7/2011	Cedar	4	8.32	17.5	8.49	692	5	50	2.5	1.65	11
9/7/2011	Dallas	15	8.97	19.9	8.09	248	3	100	0.1	0.07	8
9/7/2011	Eve	10	8.19	20.4	8.39	219	1	150	0.2	0.05	7
9/14/2011	Fish	PR25	8.99	16.3	8.37	415	2	2900	2.8	1.35	8
9/14/2011	Fish	PR26	9.13	16.2	9.14	434	5	1100	5.6	0.17	12
9/7/2011	Hackenburg	14A	9.10	21.5	7.95	250	3	0	0.0	0.1	9
9/7/2011	Hackenburg	14B	8.82	20.0	8.21	258	3	0	0.1	0.09	6
9/14/2011	Lake - Woods	PR15	8.83	17.3	4.62	431	23	0	0.4	0.64	91
9/14/2011	Little Turkey	PR11	8.71	19.3	8.41	290	2	0	0.7	0.12	7
9/14/2011	Little Turkey	PR12	8.51	18.6	8.41	297	1	0	0.4	0.17	6
9/7/2011	North Twin	3	8.28	14.3	8.20	378	90	550	5.4	0.13	442
9/7/2011	Martin	12	8.76	14.6	9.52	416	3	300	0.9	0.21	9
9/7/2011	Oliver	13	8.86	19.9	8.59	251	2	0	0.4	0.09	7

9/7/2011	Pretty	9	8.23	13.6	7.60	438	2	150	1.4	0.14	11
9/14/2011	Royer PR27		8.92	15.2	8.05	424	4	0	2.7	0.37	13
9/14/2011	Royer PR28		8.95	17.5	8.33	468	3	2500	2.3	0.38	7
9/15/2011	Shipshe PR49		10.40	17.5	9.47	403	13	600	3.0	0.54	26
9/15/2011	Shipshe PR50		10.62	19.3	9.77	216	69	0	0.3	0.455	70
9/15/2011	Shipshe PR51		8.45	15.1	7.26	362	1	0	4.5	0.17	5
9/7/2011	South Twin	2	8.28	18.1	8.77	356	2	0	0.0	0.06	10
9/7/2011	Stone	1	8.43	21.6	8.12	621	1	0	0.2	0.11	10
9/7/2011	Wall	5	8.50	18.2	8.21		2	0	0.1	0.07	12
9/7/2011	Westler	16	8.93	20.3	8.06	250	4	0	0.4	0.12	8
9/7/2011	Witmer	17	9.02	19.2	8.78	271	6	400	0.1	0.13	9

Comments	GPS
Public Access Site on 550E	41°33.262' 85°19.152'
At Swim Access Site	41°32.413' 85°24.580'
Public Access	41°34.155' 85°14.615'
Public Access	41°35.250' 85°12.238'
SE Tributary to Lake	41°43.955' 85°21.848'
Westler Outlet	41°32.778' 85°24.698'
Larry Pearson's Property on Lake	41°33.562' 85°19.376'
Outlet	
Inlet	
Dallas Lake Outlet	41°33.389' 85°25.458'
Bridge near Logan's Landing	41°33.402' 85°26.283'
Outlet	41°32.045' 85°12.157'
Inlet	
Inlet	
SE Tributary on 100W	41°43.705' 85°26.793'
East Tributary at SR 9 and 800S	41°33.304' 85°22.087'
Outlet Bridge	41°34.137' 85°24.922'

North Tributary on 800S	41°35.088' 85°15.177'
East Inlet	
South Inlet	
Inlet	
Outlet	
West Inlet	
North on 100W	41°43.735' 85°27.801'
CR 1150	41°44.665' 85°38.978'
At access site	41°43.530' 85°12.015'
Witmer Outlet	41°32.199' 85°23.830'
East Tributary Near 210E 770S	41°31.891' 85°22.978'